

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

944
NNW
> 1
1.259 mi.
6646 ft.

8664 25TH
8664 25TH AVE
BROOKLYN, NY

NY Spills S106002920
N/A

Relative:
Higher

Actual:
10 ft.

SPILLS:

Name: 8664 25TH
Address: 8664 25TH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0200836 / 2006-01-03
Facility ID: 0200836
Facility Type: ER
DER Facility ID: 123054
Site ID: 144351
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D1
SWIS: 2401
Spill Date: 2002-04-22
Investigator: RXMUSTIC
Referred To: Not reported
Reported to Dept: 2002-04-22
CID: 396
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-04-22
Spill Record Last Update: 2006-01-03

Spiller Name: Not reported
Spiller Company: SAME
Spiller Address: Not reported
Spiller Company: 999
Contact Name: CARAVELLO,GIUSEPPE
DEC Memo: ""
Remarks: "appears that the tank is leaking. they have turned this over to a tank replacement service."

All Materials:

Site ID: 144351
Operable Unit ID: 851672
Operable Unit: 01
Material ID: 522268
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported